

Highway Authority: Warwickshire Site & Location Summary 2018

All collision and casualty data pre- 2009 supplied by Warwickshire County Council on fixed camera sites. All collision and casualty data for all sites post 2009 supplied from West Mercia Police using stated grid references. All speed data supplied by Warwickshire Council.

Highway Authority: Warwickshire County
Site: 22-KCA218 - A446 London Road **Class & Status: Core - Operational - Approved: 01-Jan-05**
Grid References **Start: 415332 - 297981** **End: 415999 - 297241**

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
KCA218	415592	297621	Operational	Gatsometer BV Type 24+AUS - One Way	60
KCA219	415592	297621	Operational	Gatsometer BV Type 24+AUS - One Way	60

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
1990	2	3	2	4
1991	1	3	2	5
1992	1	2	1	2
1993	0	0	0	0
1994	0	1	0	1
1995	0	2	0	2
1996	0	1	0	1
1997	1	4	1	9
1998	0	1	0	2
1999	1	3	3	6
2000	1	3	1	3
2001	1	5	1	5
2002	0	1	0	5
2003	1	3	1	3
2004	0	0	0	0
2005	0	0	0	0
2006	1	2	1	3
2007	0	0	0	0
2008	0	1	0	1
2009	0	2	0	3
2010	0	0	0	0
2011	2	2	3	5
2012	0	1	0	4
2013	0	1	0	2
2014	0	1	0	1
2015	0	2	0	3

Average speed (mph)	85th percentile (mph)	% over
46.4	53.5	
43.8	51.3	

2016	1	0	1	0
2017	0	1	0	1

41.7	48.4	3.8
------	------	-----

Site: 22-KCA224 - A446 Lichfield Road, oppo Belfrey Class & Status: Core - Operational - Approved: 01-Jan-05
Grid References Start: 417946 - 294853 End: 418243 - 295458

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
KCA224	417826	295105	Operational	Gatsometer BV Type 24+AUS - One Way	50

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
1990	1	3	1	5
1991	0	1	0	1
1992	1	6	1	11
1993	1	1	7	8
1994	2	7	3	15
1995	1	2	1	3
1996	1	6	3	13
1997	4	8	8	15
1998	1	3	1	4
1999	1	3	1	6
2000	0	6	0	7
2001	4	5	4	5
2002	2	8	2	14
2003	0	4	0	5
2004	1	5	1	8
2005	0	2	0	4
2006	0	2	0	3
2007	1	1	1	1
2008	1	2	1	5
2009	0	2	0	4
2010	0	0	0	0
2011	0	0	0	0
2012	0	0	0	0
2013	0	0	0	0
2014	0	0	0	0
2015	0	0	0	0
2016	0	1	0	1
2017	0	0	0	0

Average speed (mph)	85th percentile (mph)	% over
40.9	49.5	
40.3	49.0	
40.7	47.5	
40.5	47.6	
40.7	48.1	
41.1	47.3	
40.8	47.2	
46.5	53.9	
36.8	42.7	
33.3	39.3	
41.7	48.4	3.8

Site: 22-KCA230 - B4117 Coventry Road,Nr Sherborne Class & Status: Core - Operational - Approved: 01-Jan-05
Grid References Start: 419996 - 287284 End: 420159 - 288116

Year	KSI	PIC	KSI	PICS
1990	0	1	0	2
1991	0	1	0	1
1992	2	5	2	12
1993	0	3	0	5
1994	1	1	1	1
1995	0	3	0	3
1996	0	3	0	3
1997	0	3	0	4
1998	0	3	0	3
1999	1	5	1	6
2000	4	4	5	6
2001	2	4	4	6
2002	0	1	0	2
2003	0	1	0	1
2004	0	3	0	4
2005	0	2	0	2
2006	0	0	0	0
2007	0	4	0	5
2008	0	3	0	7
2009	0	5	0	7
2010	1	4	1	4
2011	0	3	0	3
2012	1	0	1	0
2013	0	3	0	3
2014	0	3	0	3
2015	1	1	1	2
2016	1	2	1	2
2017	0	3	0	6

Average speed (mph)	85th percentile (mph)	% over
29.5	35.6	
30.4	35.6	
26.3	32.9	
24.2	28.7	
23.8	28.3	
23.5	27.9	
24.5	28.7	
24.2	28.9	
24.1	28.4	
24.4	25.9	
22.5	25.7	
23.8	28.5	
22.8	26.6	0.7

Site: 22-LCA221 - B4114 Tuttle Hill **Class & Status: Core - Operational - Approved: 01-Jan-04**
Grid References **Start: 434099 - 292627** **End: 434951 - 293154**

Location ID	Eastings	Northing	Location Status	Camera Model & Direction	Limit
LCA221	434519	292876	Operational	Gatsometer BV Type 24+AUS - One Way	30

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
1990	1	3	2	4
1991	1	4	1	5
1992	0	2	0	3

Average speed (mph)	85th percentile (mph)	% over

1999	3	10	3	14
2000	1	5	1	6
2001	3	9	4	13
2002	2	9	2	10
2003	1	5	2	7
2004	2	7	2	7
2005	0	2	0	4
2006	2	6	2	6
2007	0	4	0	4
2008	1	4	1	7
2009	0	0	0	0
2010	1	3	1	4
2011	0	0	0	0
2012	0	1	0	1
2013	0	2	0	7
2014	0	1	0	1
2015	0	2	0	2
2016	0	1	0	2
2017	0	1	0	1

35.2	40.8	
32.4	38.1	
31.4	36.4	
30.7	35.7	
31.5	36.6	
31.5	36.6	
32.8	38.6	
32.1	37.5	
32.5	38.1	
28.9	31.5	
25.4	29.6	
27.5	30.5	13.2

Site: 22-LCA227 - Greenmoor Road, Nr Jubilee Centre Class & Status: Core - Operational - Approved: 01-Jan-05
Grid References Start: 435065 - 290844 End: 435756 - 291600

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
LCA227	435285	291322	Operational	Gatsometer BV Type 24+AUS - One Way	30

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
1990	0	1	0	1
1991	0	0	0	0
1992	0	2	0	2
1993	1	4	1	4
1994	2	3	5	7
1995	1	1	1	2
1996	2	3	2	3
1997	0	3	0	3
1998	0	1	0	1
1999	0	1	0	1
2000	1	3	1	4
2001	1	1	1	1
2002	1	2	1	2
2003	1	1	1	1
2004	0	1	0	1

Average speed (mph)	85th percentile (mph)	% over
35.0	40.8	
32.8	38.8	
30.5	35.8	

2005	0	2	0	2
2006	1	3	1	3
2007	0	5	0	6
2008	0	3	0	3
2009	0	0	0	0
2010	0	0	0	0
2011	0	0	0	0
2012	0	0	0	0
2013	0	0	0	0
2014	1	0	1	0
2015	0	0	0	0
2016	0	4	0	6
2017	0	2	0	2

26.0	30.0	
25.9	29.9	
25.8	29.9	
26.6	30.4	
25.9	30.5	
27.5	31.3	
23.9	28.7	
22.0	25.5	
22.8	26.6	
25.3	29.6	5.7

Site: 22-LCA228 - A444 Weddington Road **Class & Status: Core - Operational - Approved: 01-Jan-04**
Grid References **Start: 436248 - 292766** **End: 436470 - 293712**
Location **Easting** **Northing** **Location Status** **Camera Model & Direction** **Limit**
ID
LCA228 436346 293226 Operational Gatsometer BV Type 24+AUS - One Way 30

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
1990	2	3	2	3
1991	1	3	1	3
1992	0	1	0	1
1993	5	9	5	10
1994	0	2	0	5
1995	0	3	0	3
1996	0	3	0	3
1997	0	0	0	0
1998	0	2	0	2
1999	0	0	0	0
2000	0	3	0	3
2001	2	5	2	6
2002	2	3	2	3
2003	0	1	0	1
2004	0	1	0	1
2005	1	1	1	1
2006	0	0	0	0
2007	0	4	0	4
2008	0	2	0	2
2009	0	2	0	2
2010	0	2	0	4

Average speed (mph)	85th percentile (mph)	% over
33.6	38.2	
33.3	37.9	
32.5	37.6	
31.9	36.0	
32.0	36.2	
32.0	36.6	
32.1	36.7	
31.8	36.5	
31.7	36.2	

2011	0	0	0	0
2012	0	0	0	0
2013	0	0	0	0
2014	0	1	0	1
2015	0	2	0	3
2016	0	0	0	0
2017	0	3	0	6

26.2	30.0	
26.1	30.0	
24.8	28.4	
33.7	39	78.1

Site: 22-LCA229 - B4113 Nuneaton Road Class & Status: Core - Operational - Approved: 01-Jan-04
Grid References Start: 435790 - 287703 End: 435873 - 288691

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
LCA229	435858	288203	Operational	Gatsometer BV Type 24+AUS - One Way	30

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
1990	1	7	1	8
1991	3	7	3	7
1992	2	5	2	5
1993	0	6	0	7
1994	0	0	0	0
1995	0	4	0	6
1996	0	4	0	4
1997	1	8	1	9
1998	1	10	1	16
1999	2	14	2	17
2000	4	14	5	17
2001	1	2	1	2
2002	1	11	1	11
2003	0	9	0	14
2004	2	8	2	10
2005	0	7	0	12
2006	2	6	2	11
2007	0	4	0	4
2008	1	5	1	8
2009	0	0	0	0
2010	0	2	0	2
2011	1	1	1	1
2012	1	1	1	3
2013	1	2	1	4
2014	2	3	2	4
2015	0	3	0	4
2016	0	2	0	2

Average speed (mph)	85th percentile (mph)	% over
30.3	35.5	
28.1	33.5	
27.3	32.1	
27.3	31.7	
26.6	31.2	
26.9	31.3	
27.4	32.0	
27.1	31.8	
28.8	32.7	
21.7	26.2	
24.5	27.9	

2017	1	3	1	6
------	---	---	---	---

34.6	40.1	78.9
------	------	------

Site: 22-MCA203 - A45 London Road **Class & Status: Core - Operational - Approved: 01-Jan-02**
Grid References **Start: 412283 - 256533** **End: 415313 - 255876**

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
MCA203	438288	274477	Operational	Gatsometer BV Type 24+AUS - One Way	50
MCA204	438939	274306	Operational	Gatsometer BV Type 24+AUS - One Way	50
MCA205	439418	274093	Operational	Gatsometer BV Type 24+AUS - One Way	50
MCA206	438792	274397	Operational	Gatsometer BV Type 24+AUS - One Way	50
MCA212	437181	275150	Operational	Gatsometer BV Type 24+AUS - One Way	50

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
1990				
1991				
1992				
1993				
1994				
1995				
1996				
1997				
1998				
1999				
2000				
2001				
2002				
2003				
2004				
2005				
2006				
2007				
2008				
2009	0	1	0	1
2010	1	1	2	1
2011	1	0	2	0
2012	1	8	1	11
2013	3	5	5	7
2014	1	0	1	2
2015	0	0	0	0
2016	1	2	1	2
2017	0	1	0	1

Average speed (mph)	85th percentile (mph)	% over
44.9	49.5	2.7
52.9	60.6	20.9

Site: 22-MCA222 - A426 Dunchurch Road

Class & Status: Core - Operational - Approved: 01-Jan-04

Grid References

Start: 449922 - 274042

End: 450173 - 274954

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
MCA222	450161	274455	Operational	Gatsometer BV Type 24+AUS - One Way	30

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
1990	1	7	1	9
1991	0	3	0	3
1992	1	7	1	7
1993	1	6	1	6
1994	2	9	2	11
1995	1	4	1	8
1996	0	2	0	3
1997	1	7	1	8
1998	0	4	0	5
1999	1	5	1	11
2000	4	8	4	10
2001	0	3	0	5
2002	0	1	0	2
2003	0	5	0	10
2004	1	4	1	5
2005	1	3	1	3
2006	0	1	0	1
2007	1	4	1	4
2008	0	0	0	0
2009	0	6	0	7
2010	0	4	0	4
2011	0	2	0	3
2012	0	3	0	3
2013	1	0	1	0
2014	0	2	0	2
2015	2	1	2	1
2016	2	4	2	5
2017	1	3	1	3

Average speed (mph)	85th percentile (mph)	% over
31.9	36.8	
34.2	40.3	
29.8	34.5	
29.5	34.4	
29.8	34.6	
29.6	34.4	
29.6	34.4	
29.9	34.6	
30.0	34.7	
27.6	31.6	
25.3	28.8	
23.2	26.6	
24.5	28.8	2.3

Site: 22-MCA231 - A428 Hillmorton Road

Class & Status: Core - Operational - Approved: 01-Jan-06

Grid References

Start: 451225 - 274137

End: 452028 - 274730

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
MCA231	451643	274439	Operational	Gatsometer BV Type 24+AUS - One Way	30
MCA232	451020	274825	Operational	Gatsometer BV Type 24+AUS - One Way	30

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
1990	1	7	1	9
1991	0	3	0	3
1992	1	7	1	7
1993	1	6	1	6
1994	2	9	2	11
1995	1	4	1	8
1996	0	2	0	3
1997	1	7	1	8
1998	0	4	0	5
1999	1	5	1	11
2000	0	1	0	1
2001	1	3	1	3
2002	1	5	1	7
2003	2	3	2	3
2004	1	3	1	4
2005	1	5	1	6
2006	0	2	0	3
2007	0	0	0	0
2008	1	4	1	5
2009	0	6	0	7
2010	0	0	0	0
2011	0	5	0	6
2012	0	4	0	4
2013	0	6	0	7
2014	0	3	0	3
2015	1	2	1	3
2016	1	1	1	2
2017	0	0	0	0

Average speed (mph)	85th percentile (mph)	% over
31.9	36.8	
34.2	40.3	
29.8	34.5	
29.5	34.4	
29.8	34.6	
29.6	34.4	
29.6	34.4	
29.9	34.6	
30.0	34.7	
27.6	31.6	
23.5	27.5	
22.6	27.7	0.9

Site: 22-MCA238 - B4429 Ashlawn Road Class & Status: Core - Operational - Approved: 01-Jan-11
Grid References Start: 450729 - 272615 End: 451788 - 273330

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
MCA238	451169	272922	Operational	Gatsometer BV Type 24+AUS - One Way	40
MCA239	451371	273045	Operational	Gatsometer BV Type 24+AUS - One Way	40

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS

Average speed (mph)	85th percentile (mph)	% over

1990	4	4	7	12
1991	0	4	0	5
1992	0	1	0	2
1993	1	4	1	4
1994	1	1	1	1
1995	1	5	1	6
1996	1	5	4	9
1997	0	1	0	1
1998	0	0	0	0
1999	1	3	1	3
2000	1	3	1	3
2001	0	2	0	6
2002	0	1	0	2
2003	1	4	2	10
2004	0	2	0	5
2005	0	2	0	2
2006	1	6	1	10
2007	2	5	3	8
2008	1	2	1	2
2009	0	3	0	4
2010	0	0	0	0
2011	1	0	1	0
2012	0	2	0	3
2013	0	2	0	2
2014	0	1	0	1
2015	0	1	0	1
2016	0	2	0	2
2017	0	2	0	3

41.7	47.4	
35.8	41.5	
35.5	41.2	
24.9	29.9	
29.4	34.8	46.2

Site: 22-MCJ508 - A4071 Bilton Road Junction May **Class & Status: Core - Operational - Approved: 01-Jan-99**
Grid References **Start: 448840 - 274334** **End: 449005 - 274445**

Location ID **Easting** **Northing** **Location Status** **Camera Model & Direction** **Limit**
 MCJ508 448918 274406 Operational Gatsometer BV Type 36 - One Way 30

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
2005				
2006				
2007				
2008				
2009	0	3	0	3
2010	0	0	0	0
2011	0	1	0	2
2012	0	1	0	1

2013	0	0	0	0
2014	1	2	1	2
2015	0	1	0	1
2016	1	0	1	0
2017	0	0	0	0

Site: 22-MCJ509 - A446 Lichfield Road **Class & Status: Core - Operational - Approved: 01-Jan-99**
Grid References **Start: 419109 - 290796** **End: 419188 - 290883**

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
MCJ509	419146	290830	Operational	Gatsometer BV Type 36 - One Way	30

Site: 22-MCJ510 - A446 Lichfield Road **Class & Status: Core - Operational - Approved: 01-Jan-99**
Grid References **Start: 419109 - 290796** **End: 419188 - 290883**

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
MCJ510	419149	290854	Operational	Gatsometer BV Type 36 - One Way	30

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
2005				
2006				
2007				
2008				
2009	0	0	0	0
2010	0	1	0	1
2011	0	0	0	0
2012	1	0	1	0
2013	0	0	0	0
2014	0	0	0	0
2015	0	1	0	2
2016	0	0	0	0
2017	0	1	0	1

Site: 22-MCJ513 - B4087 Tachbrook Road **Class & Status: Core - Operational - Approved: 01-Jan-99**
Grid References **Start: 431835 - 265149** **End: 431926 - 265249**

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
MCJ513	431872	265184	Operational	Gatsometer BV Type 36 - One Way	30

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
2005				
2006				
2007				

2008				
2009	0	2	0	4
2010	0	2	0	2
2011	0	2	0	2
2012	0	0	0	0
2013	0	2	0	3
2014	1	2	1	2
2015	0	2	0	2
2016	0	0	0	0
2017	1	0	1	0

Site: 22-MCJ514 - A425 High Street **Class & Status: Core - Operational - Approved: 01-Jan-99**
Grid References Start: 431827 - 265147 **End: 431930 - 265248**

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
MCJ514	431891	265195	Operational	Gatsometer BV Type 36 - One Way	30

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
2005				
2006				
2007				
2008				
2009	0	2	0	4
2010	0	2	0	2
2011	0	2	0	2
2012	0	1	0	1
2013	0	3	0	4
2014	1	3	1	3
2015	0	2	0	2
2016	0	1	0	1
2017	0	0	0	0

Site: 22-NCA200 - A435 Birmingham Road **Class & Status: Core - Operational - Approved: 01-Jan-02**
Grid References Start: 407800 - 259188 **End: 408300 - 261209**

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
NCA200	408156	259693	Operational	Gatsometer BV Type 24+AUS - One Way	40
NCA201	408025	260224	Operational	Gatsometer BV Type 24+AUS - One Way	40
NCA202	407964	260717	Operational	Gatsometer BV Type 24+AUS - One Way	40

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS

Average speed (mph)	85th percentile (mph)	% over
---------------------	-----------------------	--------

2001	0	3	0	4
2002	0	2	0	4
2003	3	5	3	6
2004	1	2	1	3
2005	0	3	0	3
2006	2	3	2	3
2007	0	1	0	1
2008	0	0	0	0
2009	0	1	0	1
2010	0	3	0	4
2011	0	1	0	1
2012	0	1	0	2
2013	0	2	0	4
2014	0	3	0	4
2015	0	2	0	4
2016	1	1	1	1
2017	1	0	1	1

37.1	41.8	
37.0	41.7	
33.4	38.2	
28.4	32.9	
26.6	30.1	
27.1	30.3	
26.9	30.2	
25.3	29.3	
25.6	29.6	3.9

Site: 22-PCJ503 - A452 Dale Street (South) Junction Class & Status: Core - Operational - Approved: 01-Jan-95
Grid References Start: 431456 - 265560 End: 431468 - 266512

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
PCJ503	431471	266055	Operational	Gatsometer BV Type 36 - One Way	30

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
2005				
2006				
2007				
2008				
2009	0	0	0	0
2010	0	0	0	0
2011	0	0	0	0
2012	0	0	0	0
2013	0	0	0	0
2014	0	0	0	0
2015	0	0	0	0
2016	0	1	0	1
2017	0	0	0	0

Site: 22-PCJ501 - A445 Lillington Avenue Class & Status: Core - Operational - Approved: 01-Jan-95
Grid References Start: 431710 - 266703 End: 431798 - 266802

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
-------------	---------	----------	-----------------	--------------------------	-------

Site: 22-PCJ502 - Kenilworth Road **Class & Status: Core - Operational - Approved: 01-Jan-95**
Grid References Start: 431710 - 266703 End: 431798 - 266802

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
PCJ502	431760	266770	Operational	Gatsometer BV Type 36 - One Way	30

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
2005				
2006				
2007				
2008				
2009	0	0	0	0
2010	0	0	0	0
2011	0	1	0	1
2012	0	0	0	0
2013	0	0	0	0
2014	0	1	0	1
2015	0	0	0	0
2016	0	1	0	1
2017	0	0	0	0

Site: 22-PCJ504 - Warwick Street **Class & Status: Core - Operational - Approved: 01-Jan-95**
Grid References Start: 431420 - 266012 End: 431524 - 266114

Location ID	Easting	Northing	Location Status	Camera Model & Direction	Limit
PCJ504	431482	266062	Operational	Gatsometer BV Type 36 - One Way	30

Year	COLLISIONS		CASUALTIES	
	KSI	PIC	KSI	PICS
2005				
2006				
2007				
2008				
2009	0	0	0	0
2010	0	0	0	0
2011	0	1	0	1
2012	0	0	0	0
2013	0	4	0	4
2014	0	0	0	0
2015	0	1	0	1
2016	0	1	0	1
2017	0	0	0	0